
<u>LEGEND</u> ±	MORE OR LESS
A/C	AIR CONDITIONING UNIT
A.K.A.	AMERICAN CONGRESS ON SURVEYING & MAPPING ALSO KNOWN AS
	AMERICAN LAND TITLE ASSOCIATION CERTIFIED CORNER RECORD
	CONCRETE ELEVATION
FD.	FOUND
	LICENSED BUSINESS REGISTERED LAND SURVEYOR
	LAND SURVEYOR NUMBER
<i>I.D</i> .	IDENTIFICATION OFFICIAL RECORDS BOOK
PID#	TAX PARCEL IDENTIFICATION NUMBER
	PAGE PLAT BOOK
	LENGTH RADIUS
Δ	CENTRAL ANGLE (DELTA) CHORD LENGTH
CB	CHORD BEARING
POC	POINT OF BEGINNING POINT ON CURVE (NON-TANGENT)
	POINT OF CURVATURE POINT OF TANGENCY
	POINT OF CURVATURE POINT OF TANGENCY
PRC	POINT OF REVERSE CURVATURE
PNT	POINT OF COMPOUND CURVATURE POINT OF NON-TANGENCY
NAVD NSPS	NATIONAL SOCIETY OF PROFESSIONAL SURVEYORS NORTH AMERICAN VERTICAL DATUM
(C) (M)	CALCULATED MEASUREMENT FIELD MEASUREMENT
(), ( <i>P</i> ) ( <i>D</i> )	PLAT MEASUREMENT
FDOT	FLORIDA DEPARTMENT OF TRANSPORTATION
ECP	FEDERAL EMERGENCY MANAGEMENT AGENCY ELLIPTICAL CONCRETE PIPE
	BARBED WIRE FENCE CHAIN LINK FENCE
WPF	
OHU	OVERHEAD UTILITIES CENTERLINE
R/W	RIGHT OF WAY
<i>I.P</i> .	CONCRETE MONUMENT IRON PIPE
	IRON ROD IRON ROD AND CAP
NOID	NO IDENTIFICATION WITH
	GENERAL CARDINAL DIRECTION (NORTHERLY, ETC)
527, & WET	FOUND CONCRETE MONUMENT (AS NOTED)
0 (0)	FOUND NAIL (AS NOTED) FOUND NAIL & DISK (AS NOTED)
۲	FOUND 5/8" IRON ROD & CAP (AS NOTED)
•	FOUND IRON PIPE (AS NOTED) FOUND IRON ROD (AS NOTED)
(A) (D)	SET NAIL & DISK (LB 4709) SET 5/8" IRON ROD AND CAP (LB 4709)
S	SANITARY MANHOLE
	SEWER VALVE
	STORM MANHOLE CATCH BASIN
	TELEPHONE MANHOLE WELL (SIZE NOTED)
×	WATER VALVE
- A	BACKFLOW PREVENTOR FIRE HYDRANT
	WATER SPIGOT CONCRETE UTILITY POLE
	METAL UTILITY POLE WOOD UTILITY POLE
$\leftarrow$	GUY ANCHOR
- <del>0</del> -	LIGHT POLE SIGN
Ē	BOLLARD ELECTRIC RISER
	ELECTRIC TRANSFORMER ELECTRIC METER
	CABLE TELEVISION RISER PULLBOX (ELECTRIC)
PB FO	PULLBOX (FIBER)
89 11 12 12 12 12 12 12 12 12 12 12 12 12	PULLBOX (TELEPHONE) PULLBOX (TRAFFIC)
B M □	PULLBOX (TELEVISION) TELEVISION RISER
FO	UNDERGROUND FIBER OPTIC CABLE MARKER
G X TV X	UNDERGROUND GAS MARKER UNDERGROUND CABLE TELEVISION MARKER
	UNDERGROUND ELECTRIC MARKER UNDERGROUND TELEPHONE MARKER
W	UNDERGROUND WATER LINE MARKER
rw ⊠ ₽	UNDERGROUND RECLAIM WATER LINE MARKER FLAG POLE
	MAILBOX GATE POST
тв	—⊶
TS	TOE OF SLOPE
	6 EXISTING CONTOUR
	CONCRETE AREA
	ASPHALT AREA
	× 10.00 SPOT ELEVATION (HARD SURFACE)
	× 10.0 SPOT ELEVATION (HARD SORFACE) × 10.0 SPOT ELEVATION (GROUND)
L	

TREE LEGEND: (CALIPER NOTED INSIDE SYMBOL) 🔵 BAY CAMPHOR () CEDAR CHERRY CHINABERRY CITRUS CYPRESS DOGWOOD ELM 💥 GUM HACKBERRY 🛞 HICKORY HOLLY LAUREL OAK 📸 LIVE OAK MAGNOLIA MAPLE MIMOSA MISCELLANEOUS En OAK TURKEY OAK PALM B PECAN Me PINE SYCAMORE WATER OAK



BROKEN OAK DRIVE ROUTE SURVEY SECTION 5 , TOWNSHIP 19 SOUTH, RANGE 23 EAST SUMTER COUNTY, FLORIDA



VICINITY MAP

## SURVEY NOTES:

- 1. THIS IS A TOPOGRAPHIC SURVEY AS DEFINED IN CHAPTER 5J-17.050 (11) FLORIDA ADMINISTRATIVE CODE.
- 2. BEARINGS AND COORDINATES SHOWN HEREON ARE FIELD MEASURED AND BASED ON THE FLORIDA STATE PLANE COORDINATE SYSTEM, WEST ZONE, NORTH AMERICAN DATUM (NAD) OF 1983 WITH 2011 ADJUSTMENT.
- 3. ACCORDING TO FEDERAL EMERGENCY MANAGEMENT AGENCY'S FLOOD INSURANCE RATE MAP (FIRM) NUMBER 12119C0132D, SUMTER COUNTY, FLORIDA, EFFECTIVE DATE OF SEPTEMBER 27, 2013, THE PROPERTY DESCRIBED HEREON LIES PARTIALLY WITHIN ZONE "X" (AREAS OUTSIDE THE 0.2% ANNUAL CHANCE FLOOD), AND PARTIALLY WITHIN ZONE "A" WITH NO BASE FLOOD ELEVATION DETERMINED. FLOOD ZONES HAVE BEEN SCALED AND DEPICTED HEREON.
- 4. THIS SURVEY WAS PREPARED WITHOUT THE BENEFIT OF A TITLE COMMITMENT. ENCUMBRANCES SUCH AS EASEMENTS MAY EXIST THAT ARE NOT SHOWN HEREON.
- 5. NORTH-SOUTH AND EAST-WEST TIES TO FOUND MONUMENTATION AND IMPROVEMENTS ARE BASED ON CARDINAL DIRECTION, UNLESS ENDING IN "-LY" (NLY, ELY, SLY, WLY) WHICH ARE PERPENDICULAR TIES TO THE BOUNDARY LINE.
- 6. WETLAND AREAS, IF EXISTING, WERE NOT ADDRESSED AS A PART OF THIS SURVEY.
- 7. UNDERGROUND UTILITIES AND FOUNDATIONS WERE NOT LOCATED
- 8. THIS SURVEY MAP AND REPORT OR THE COPIES THEREOF ARE NOT VALID WITHOUT THE ORIGINAL OR ELECTRONIC SIGNATURE AND SEAL OF A FLORIDA LICENSED SURVEYOR AND MAPPER.
- 9. RECORDING REFERENCES (SUCH AS OFFICIAL RECORDS BOOK AND PAGE, AND PLAT BOOK AND PAGE) SHOWN HEREON, REFER TO DOCUMENTS RECORDED IN THE OFFICIAL RECORDS OF SUMTER COUNTY, FLORIDA.
- 10. ELEVATIONS SHOWN HEREON ARE PURSUANT TO THE NORTH AMERICAN VERTICAL DATUM OF 1988 AND WERE ESTABLISHED DIFFERENTIAL LEVELING METHODS. THE ORIGINATING BENCHMARK FOR THE ELEVATIONS DEPICTED HEREON IS NATIONAL GEODETIC SURVEY BENCHMARK # 23135 A, SAID POINT BEING A SURVEY DISC SET IN A WATER TANK PEDESTAL STAMPED "23135 A" AND HAVING AN ELEVATION OF 83.03 FEET.
- 11. THE AERIAL IMAGE DEPICTED HEREON IS DATED 2020 AND WAS OBTAINED FROM THE FLORIDA DEPARTMENT OF TRANSPORTATION.
- DISTANCES AND ACREAGES SHOWN HEREON ARE MEASURED IN U.S. SURVEY FEET AND DECIMALS THEREOF. MEASUREMENTS DEPICTED HEREON ARE FIELD DERIVED UNLESS OTHERWISE NOTED.
  UNLESS OTHERWISE NOTED HEREON, THERE APPEARS TO BE NO DEEDED OR DEDICATED ROAD RIGHT-OF WAY FOR
- BROKEN OAK DRIVE OR NORTH ST. CLAIR STREET. RIGHT-OF-WAY APPEARS TO BE BY MAINTENANCE PURSUANT TO CHAPTER 95.361, FLORIDA STATUTES. NO RIGHT-OF-WAY WIDTH WAS DETERMINED IN THESE AREAS.

